



• MANUFACTURERS OF WIPLINE FLOATS & SKIS  
• SPECIALISTS IN AIRCRAFT MODIFICATION

1700 Henry Avenue - Fleming Field  
South St. Paul, MN 55075  
651-451-1205

Rev / Latest Rev  
B / 11-26-08

Original Release  
11-20-08

Prepared by  
Ellen Parker

Aircraft Make / Model

Float / Ski Model  
Wipline 10000 Floats

1  
2

FAA Reviewed



Title  
Wipline 10000 floats baggage floor repair

**ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA**

## **SERVICE KIT: 74**

**EFFECTIVITY:** All 10000 floats up to and including 10084A

**COMPLIANCE:** This Service Kit is to be complied with as needed based on the findings of regular inspections inside the baggage compartments. Later serial numbered floats should not encounter this problem as the reliefs in the floor and reinforced corners of the central panel as shown on page 2 were incorporated into production.

**BACKGROUND INFORMATION:** A few operators have experienced the baggage bulkheads cracking. After investigation it was determined this can happen because the baggage floor flexes under loads and puts pressure on the nearby bulkheads. Refer to Service Letter 101 for more information.

**METHOD OF COMPLIANCE:** Install included parts with Service Kit 1002760 as per drawing 1002760. Use sealant between all mating parts, rivets are not included in the kit.

**SHOP HOURS REQUIRED:** Varies based on floats.

**WARRANTY:** Not Applicable

**COMPLIANCE:** Required if cracks are present in the bulkheads, optional if they are not.

