

 <p style="text-align: center;"> • MANUFACTURERS OF WIPLINE FLOATS & SKIS • SPECIALISTS IN AIRCRAFT MODIFICATION </p> <p style="text-align: center; font-size: small;"> 1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205 </p>			Rev / Latest Rev. Date A / 4-15-09
			Original Release 4-15-09
Prepared by Ellen Parker	Aircraft Make / Model Fire Boss	Float / Ski Model 10000 Amphibious floats	Page 1 1
FAA Reviewed <input checked="" type="checkbox"/>	Title Fire Boss spin-on hydraulic filter revision		
ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA			

SERVICE LETTER: 103

EFFECTIVITY: This service kit needs to be installed on 10089A & 10090A and older serial numbers. Serial numbers after this cut-off will have this spin-on filter added during production.

COMPLIANCE: Mandatory at next 100 Hr Inspection. Refer to Service Kit 75 for detailed instructions.

BACKGROUND INFORMATION: Some customers have encountered ongoing problems with hydraulic fluid contamination. Initially, Wipaire engineering added additional filtering modules with varying success based on environment. At this time, we are solving this issue definitively and will increase the ease of maintenance by adding a standard spin-on filter with a pop-out gage so the pilot can see on a preflight if the filter is clogged and bypassing.

METHOD OF COMPLIANCE: Refer to Service Kit 75 for part numbers and installation instructions.

SHOP HOURS REQUIRED: 2 Hours

WARRANTY: Parts and Labor for floats manufactured up to 1 year earlier than the initial release of this service letter. For floats manufactured previous to one year earlier than the initial release of this service letter, parts only will be warranted.

COMPLIANCE: Mandatory