

Wipaire Worldwide Anywhere, Anytime

SERVICE LETTER: 11

<u>SUBJECT</u>: Installation of new electric hydraulic pump motor

MODEL FLOAT: 3730 on Cessna 206 & 185 6000 on DeHaviland Beaver MK I & MK III 8000 on Cessna Caravan

<u>SERIAL #</u>: 3730 ----S/N 37652 & down 6000 ----S/N 60078 & down 8000 ----S/N 80006 & down

COMPLIANCE REQUIRED: At owner's discretion

## BACKGROUND INFORMATION:

The electric motor has been changed by the manufacturer. It is now 1 1/2" longer. The change prevents demagnetizing the internal magnets in the motor. This change will increase the life of the motor.

METHOD OF COMPLIANCE: Install Service Kit #9

PARTS REQUIRED: See Service Kit #9

SHOP HOURS REQUIRED: 3 hours

Date: 6-9-87 Page: 1 of 1