



WIPLINE FLOATS • SKIS • MODIFICATIONS • AIRCRAFT SALES  
AVIONICS • INTERIOR • MAINTENANCE • PAINT REFINISHING

## SERVICE LETTER 186

### DEHAVILLAND DHC-6-300, -200 PLACARD SPEED CORRECTION

<b>Aircraft Makes/Model(s):</b>	<b>Float Model(s):</b>	<b>Compliance:</b> Mandatory	<b>By:</b> MAS
DeHavilland DHC-6-200 & DHC-6-300	13000 Series	<b>Part Number:</b> 1009887	<b>Approved:</b> DRH
		<b>Date:</b> 3/13/2026	<b>Revision:</b> A

#### LOG OF REVISIONS

Revision	Description	Date
A	Initial release	3/13/2026

FAA approval has been obtained for technical data in this publication that affects STC or TSO design compliance.

#### EFFECTIVITY:

This service letter applies to DeHavilland models DHC-6-300 and DHC-6-200 when equipped with Wipline model 13000 amphibian or seaplane floats installed per STC SA2CH.

#### COMPLIANCE:

Mandatory compliance

#### BACKGROUND:

When the DeHavilland DHC-6-400 variant was added to accommodate 13000 amphibian/seaplane floats, the speed placard references were shared, based on the -300/400 landplane test flight data with both variants using 105 KIAS/10 flaps. Later, recalculations of flight test data (based on -300 landplane) led to the removal of the -300/-400 using a joint placard in lieu of individual speed calculation placards showing the new 102 KIAS/10 flap calculations. This service letter and its associated kits correctly reference the -200 and -300 models' airspeed calculations.

#### COMPLIANCE METHOD:

If equipped with a speed placard showing -400 in the upper-left description, remove existing speed placard and replace it with new placard as shown in the Work Instruction section of this service letter.

#### APPROXIMATE SHOP HOURS:

N/A

#### WARRANTY INFORMATION:

This service letter does not include warranty for labor or parts.

#### TECHNICAL DATA:

Copies of this service letter, associated service kit (if applicable), float service manual, and float parts manual are available at [www.wipaire.com](http://www.wipaire.com).

1700 Henry Ave - Fleming Field (KSGS), South St. Paul, MN 55075

Phone: 651.451.1205 | Fax: 651.457.7858

[www.wipaire.com](http://www.wipaire.com)



## WORK INSTRUCTION

1. Remove existing POH supplement and speed placard and replace with new supplement and placard included in the appropriate service kit shown below.

### ITEMS PROVIDED IN SERVICE KIT 1009887-01 (AMPHIBIAN FLOATS ONLY)

QTY	PART NUMBER	DESCRIPTION
1	7B3-4103 (Rev E or later)	PLACARD, OPERATION LIMITS, AMPHIBIAN, DHC6-300, -200
1	POHSA2CH-A-1 (Rev D or later)	AIRPLANE FLIGHT MANUAL SUPPLEMENT, DHC-6-300, -200 (WITH STC SA0225LA) ON 13000A FLOATS

### ITEMS PROVIDED IN SERVICE KIT 1009887-02 (SEAPLANE FLOATS ONLY)

QTY	PART NUMBER	DESCRIPTION
1	7B3-4101 (Rev C or later)	PLACARD, OPERATION LIMITS, SEAPLANE, DHC6-300, -200
1	POHSA2CH-S-2 (Rev J or later)	AIRPLANE FLIGHT MANUAL SUPPLEMENT, DHC-6-300, -200 (WITH STC SA0225LA) ON 13000S FLOATS

## AIRCRAFT CLOSING AND RETURN TO SERVICE

1. Upon completion of inspection, enter information in Aircraft Logbook for completion of Wipaire Service Letter 186.