



Wipaire Worldwide
Anywhere, Anytime

SERVICE LETTER: #15

SUBJECT: Hydraulic oil contamination in the landing gear hydraulics.

FLOAT MODEL: All Amphibian Floats.

COMPLIANCE REQUIRED: At owner's discretion.

BACKGROUND INFORMATION: Contamination has been reported by some customers in various locations and storage situations. This contamination is a variety of dirt, water, and fungi growth (Black Mass) that can collect on the filter screen and plug it if not cleaned. The fungi growth grows at the interface between water and oil and float storage variables may be a factor.

METHOD OF COMPLIANCE: It is recommended that the oil and filter be checked for contaminants. Remove contaminated oil and clean the filter screen. This should be done after prolonged storage or at annual inspection.

PARTS REQUIRED:

SHOP HOURS REQUIRED:

Date: 2/19/88

Page: 1 of 1