

DATE: APRIL 25, 2002

REISSUED: MARCH 10, 2004

SERVICE KIT: #34

SUBJECT: Modification – Landing Gear

MODEL: 2100 Floats S/N 21232 DN. and 2350 Floats S/N 21032 and DN.

<u>Item</u>	<u>Quantity</u>	<u>Part No.</u>	<u>Description</u>
1.	2	21A04000-073 (10B2-6015-1)	Ass'y- Shock Strut (2100 Float)
2.	2	23A04000-113 (10B2-6015-2)	Ass'y- Shock Strut (2350 Float)
3.	2	21A05000-018 (10C2-6043)	Ass'y-Arm Retract
4.	2	21A04454-006 (10B3-6107)	Shaft-Axle
5.	1	21A05000-016 (10B2-6046-2)	Ass'y-Arm RH
6.	1	21A05000-017 (10B2-6046-1)	Ass'y-Arm LH
7.	4	NAS6204-17	Bolt
8.	8	AN960-416	Washer (NAS1149FO463P)
9.	4	MS21083N4	Nut
10.	4	21A05520-003 (10A3-6106)	Roller
11.	4	1095K43	Zerk
12.	8	1095K41 (4 on 2 Assemblies)	Zerk
13.	2	21A05705-002 (10A3-6280)	Clevis – Retract Arm
14.	2	21A05260-005 (10A3-6542)	Spacer – Hyd. Cylinder
15.	2	AN960PD516	Washer (NAS1149DO563J)
16.	2	21A04547-004	Bushing
17.	1	No. 52	Service Letter

Instructions:

1. Reference sheet 2 for Main Gear Assembly
2. Service Manual

## KIT 34

