


| | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|-----------------------------------------------------------|-------------------------------------------------|
|  <p style="color: red; font-size: small;">• MANUFACTURERS OF WIPLINE FLOATS & SKIS • SPECIALISTS IN AIRCRAFT MODIFICATION</p> <p style="font-size: x-small;">1700 Henry Avenue - Fleming Field South St. Paul, MN 55075 651-451-1205</p> | | | Rev / Latest Rev. Date A / 1-30-09 |
| | | | Original Release 1-30-09 |
| Prepared by Ellen Parker | Aircraft Make / Model | Float / Ski Model All Wipline Amphibious Floats | Page 1 |
| FAA Reviewed <input checked="" type="checkbox"/> | Title Lake and Air Gear Advisory Information | | |
| ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA | | | |

SERVICE LETTER: 102

EFFECTIVITY: All aircraft equipped with Lake and Air Landing Gear Position Advisory System installed in accordance with STC SA39CH.

COMPLIANCE: **Compliance is mandatory.** Please refer to Lake and Air Service Letter 1.
 Contact Lake and Air:
 Lake & Air, Inc.
 1700 Henry Avenue
 South St Paul, MN 55075
 Ph: 651.552.9227 or 1.888.525.3247
 Fax: 651.552.9263
 www.lakeandair.com
 sales@lakeandair.com

BACKGROUND INFORMATION: There have been reports of pilots pulling the gear advisory circuit breaker when the system is operating normally. **This renders the advisory system inoperable and does not provide critical gear position advisories to the pilot. Landing with the gear in the wrong position can cause serious injury or death!**

METHOD OF COMPLIANCE: Refer to Lake and Air Service Letter 1

WARRANTY: Not applicable