

 <p style="text-align: center;"> <b>• MANUFACTURERS OF WIPLINE FLOATS &amp; SKIS</b>  <b>• SPECIALISTS IN AIRCRAFT MODIFICATION</b> </p> <p style="text-align: center; font-size: small;"> 1700 Henry Avenue - Fleming Field  South St. Paul, MN 55075  651-451-1205 </p>			Rev
			Date 04/06/06
Prepared by Ellen Parker	Aircraft Make / Model AT-802	Float / Ski Model 10000 Amphibious Floats	Page 1
FAA Reviewed <input checked="" type="checkbox"/>	Title AT-802 Fire Boss Brake Line Lengthening		
<b>ALL INFORMATION IN THIS SERVICE DOCUMENT BASED ON FAA APPROVED DATA</b>			

**SERVICE KIT: # 57**

**DATE: APRIL 6, 2006**

**EFFECTIVITY: All AT-802 aircraft with Wipline 10000 Amphibious Floats serial number 10001-10052.**

**COMPLIANCE: Not Mandatory. This Service Kit is optional and intended for ease of maintenance on the brake system.**

**METHOD OF COMPLIANCE:**

**Order from Wipaire Parts Department and install the parts listed below. Install new hoses with the same routing and methods as the originals.**

**PARTS REQUIRED:**

**P/N 13A04000-068                      Qty. 4**

**REPAIR HOURS REQUIRED: 2**

**WARRANTY: None**